



Massachusetts Department of Environmental Protection  
Bureau of Resource Protection – Watershed Permitting Program  
**Sanitary Sewer Overflow (SSO)/Bypass  
Notification Form**

FOR DEP USE ONLY

Tax Identification Number

**A. Reporting Facility**

Important: When filling out forms on the computer, use only the tab key to move your cursor - do not use the return key.



See DEP Regional Office telephone and fax numbers at the end of this form.

1. Facility Information

HULL MA WPCF  
Reporting Sewer Authority

MA0101231  
Permit #

2. Authorized Representative Transmitting Form:

ARAM  
First Name

VARJABEDIAN  
Last Name

781-925-0906  
Telephone No.

PLANT MANAGER  
Title

avarjabedian@woodardcurran.com  
E-mail Address

**B. Phone Notifications:** EMAIL NOTIFICATIONS - ALL

1. MassDEP staff contacted:

DAVID  
first name

BURNS  
last name

Date/Time contacted:

11/6/15  
Date

2:40  
Time

☐ am ☒ pm

2. EPA staff contacted:

DAVID  
first name

TURIN  
last name

Date/Time EPA contacted:

11/6/15  
Date

2:40  
Time

☐ am ☒ pm

3. Board of Health contacted:

JOYCE  
First Name

SULLIVAN  
Last Name

Date/Time contacted:

11/6/15  
Date

2:40  
Time

☐ am ☒ pm

4. Others notified (select all that apply);

☐ Conservation Commission

☐ Harbormaster

☐ Shellfish Warden

☒ Division of Marine Fisheries

☐ Downstream Drinking Water Supplier

☐ Watershed Association

☐ Beach Resource Manager

☐ Other:

RYAN JOYCE  
(specify)

**C. SSO Information**

1. SSO Discovered:

HULL PSC NOTIFIED ON 11-6-15  
Date

~9:50  
Time

☒ am ☐ pm

By:

BUT PIPE WAS BROKEN ON 11/5/15 + temporarily REPAIRED

2. SSO Stopped:

WAS STOPPED 11-5-15  
Date

AT APPROX 6:00  
Time

☐ am ☒ pm

3. SSO Discharge from:

☐ Sanitary Sewer Manhole

☐ Pump Station

☐ Backup into Property

☒ Other:

6" PVC SEWER LINE  
(specify)

4. SSO Discharge to: ☒ Ground Surface (no release to surface water)

☐ Direct to Receiving Water

(surface water)

☐ Catch basin to Receiving Water

(surface water)

☐ Backup into Property Basement



**Massachusetts Department of Environmental Protection**  
Bureau of Resource Protection – Watershed Permitting Program  
**Sanitary Sewer Overflow (SSO)/Bypass**  
**Notification Form**

FOR DEP USE ONLY

Tax Identification Number \_\_\_\_\_

**C. SSO Information (cont.)**

Location: 045 NANTASKET AVE BY MEZZO MARÉ RESTAURANT  
(Description of discharge site or closest address)

5. Estimated SSO Volume at time of this Report: CAN NOT BE DETERMINED

Method of Estimating Volume: \_\_\_\_\_

6. Cause of SSO Event:

☐ Rain Event    ☐ Pump Station Failure    ☐ Insufficient Capacity in System

☐ Treatment Unit failure

☐ Sewer System Blockage:    ☐ Pipe Collapse    ☐ Root Intrusion    ☐ Grease Blockage

☒ Other: PIPE BROKEN WHILE EXCAVATION BEING DONE  
(Specify) by NGRID-GAS CO.

7. Corrective Actions Taken:

HULL PSC notified Woodward & Curran AT 9:15am 11/6/15.  
WTC staff dispatched to location, found/inspected area.  
+ Hub Construction contacted to perform the repair.

Impact Area cleaned and/or disinfected:    ☐ Yes    ☐ No

N/A

Corrective Actions Completed:    ☒ Yes    ☐ No

PIPE REPAIRED BY HUB CONSTRUCTION

**D. Comments/Attachments/Follow-up**

I wish to provide (select all that apply):

☐ Attachment    ☐ Additional comments below:    ☐ No additional comments or attachments

Additional comments and planned actions:

Spoke with David Burns - re 245 NANTASKET Ave AT  
2:55 p.m.



**Massachusetts Department of Environmental Protection**  
**Bureau of Resource Protection – Watershed Permitting Program**  
**Sanitary Sewer Overflow (SSO)/Bypass**  
**Notification Form**

FOR DEP USE ONLY

Tax Identification Number

---

**E. Certification Statement**

I certify under penalty of law that this document and all attachments were prepared under my direction or supervision in accordance with a system designed to assure that qualified personnel properly gather and evaluate the information submitted. Based on my inquiry of the person or persons who manage the system, or those persons directly responsible for gathering the information, the information submitted is, to the best of my knowledge and belief, true, accurate, and complete. I am aware that there are significant penalties for submitting false information, including the possibility of fine and imprisonment for knowing violations.

*Aram Varjabedian*

Signature of Authorized Representative

11-6-15

Date Signed

Please keep a copy of this report for your records. When submitting additional information, include the MassDEP Incident Number from this report.

---

**MassDEP Regional Office and EPA Telephone and Fax Numbers:**

Northeast Region	Phone: 978-694-3215	Fax: 978-694-3499
Southeast Region	Phone: 508-946-2750	Fax: 508-947-6557
Central Region	Phone: 508-792-7650	Fax: 508-792-7621
Western Region	Phone: 413-784-1100	Fax: 413-784-1149
EPA Contact	Phone: 617-918-1870	Fax: 617-918-0870
DEP 24-hour emergency	Phone: 888-304-1133	





## Hull Wastewater

## Work Order

### Work Order Information

**Date:** 11/06/2015

**Type:** Corrective Maintenance

**Status:** In Process  
*completed*

**Asset:** 22 - WW -  
sewers/pipes/force mains

**Priority:** High

**Reason:** Operational

### Description of Issue

**Description:** National grid broke pipe in front of Mazza mare<sup>2</sup>


**Notes:** Called Hub construction to repair broken pipe

### Actions Taken

**Staff:** Eric Sutton

**Service:** Went to location observed there was a broken sewer pipe called plant Mgr (aram) he notified Jim Dow and Hub construction Hub on way to repair pipe

### Photos



## Aram Varjabedian

---

**To:** 'david.burns@state.ma.us'; 'Turin, David'; Joyce, Ryan (FWE); jsullivan@town.hull.ma.us  
**Cc:** Dow, James; Kevin Stetson  
**Subject:** 245 Nantasket Ave - SSO Notification  
**Attachments:** 245 nantasket ave.jpg

Good Afternoon:

This SSO notification is for 245 Nantasket Ave [by Mezzo Mare' restaurant] A 6-inch PVC sewer line was broken, while National Grid was performing gas line excavation work last night at approximately 6:00pm.. The Hull Sewer Department was notified this morning at approximately 9:50am. Staff were dispatched to the location to inspect & evaluate. The 6-inch gravity sewer line had been patched last night by the excavating crew to minimize/stop any sewage from leaking into the excavated hole. A permanent repair was done by Hub Construction this morning, after notification.

No estimation of sewage can be made, since we were not notified last evening, but the amount appears to be minimal.

A complete SSO Notification form will be completed and forwarded.

Sincerely,

Aram Varjabedian

Aram Varjabedian  
Plant Manager  
Hull Wastewater Treatment Facility  
1111 Nantasket Avenue |Hull, MA 02045  
Phone 781.925.0906 | Fax 781.925.3056 | Cell 339.214.8334  
[www.woodardcurran.com](http://www.woodardcurran.com)



COMMITMENT & INTEGRITY DRIVE RESULTS







BATH HOUSE

REVISIONS BY  
11/6/15  
CS

NAVY ASKET AVE

D=3' At P.L.  
6" PVC Sewer / 56'-8" From MH To  
Cross over of gas line  
And sewer line  
3' Deep

6" HDC VC Pipe  
TRAFFIC PIPE  
12'

SHORE DR.

gas line  
land mark

gas line

18' OFF  
center  
of Building

sewer line  
Angle

56'-8"

55'

To center  
of MH

M.H. COVER AT GRADE

22" 6"

1.5' OFF BID

1000  
gal  
GROSS  
TRAP

OCEAN BAR # BR11  
245 NAVY ASKET

80'

total to MH

111'

20'

18'

G-45